



UNITED STATES DEPARTMENT OF COMMERCE
Patent and Trademark Office
ASSISTANT SECRETARY OF COMMERCE AND
COMMISSIONER OF PATENTS AND TRADEMARKS
P.O. Box 1450
Alexandria, VA 22313-1450

January 8, 2008

KENYON & KENYON LLP
1500 K STREET N.W.
SUITE 700
WASHINGTON DC 20005

Patent No. : 7,133,768 B2
Inventor(s) Yoshio Mukaiyama
Issued : November 7, 2006
For **VEHICULAR DRIVING SUPPORT
SYSTEM AND VEHICULAR CONTROL
SYSTEM**
Doc. No. **10517/209**

To Whom It May Concern:

The Certificate of Correction issued on January 8, 2008, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

On page 1 of 4 of the issued certificate of correction, the statement --Delete drawing sheet 4 of 8 and substitute therefore the attached drawing sheet 4 of 8-- is to be inserted below the first correction. The correction to FIG. 4 was incorporated on the title page and drawing sheet 4 of 8 was changed to display the correct FIG. 4, but no statement was entered on issued certificate of correction pertaining to the correction. A superseding cofc will be issued to include statement to the corrected drawing sheet 4 of 8.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson
(703) 308-9390 ext. 111
For Cecelia Newman, Supervisor
Decisions & Certificates of Correction Branch
(703) 305-8309 / 703-308-9390 ext. 102
cbn